TEST REPORT

Applicant: Dongguan Qunan Plastic Industrial Co., Ltd
Address: Cross road Dongguan Qishi town Dongshan kapok Industrial Zone

The following sample(s) was/were submitted and identified on behalf of the client as:

Sample name:	SuperSafeGlas
Sample size:	150*200mm
Thickness:	3+1.52+3mm
Material:	SuperSafeGlas
Number of samples:	5pcs
Sample Received:	2017-09-27
Testing Period:	2017-09-27～2018-01-29

Test item:	Salt spray test
Test standard:	ASTM B117-16

Test results: Please refer to next page

Wrote by: pany Reviewed by: Cole

Approved by: Wetow Huang Date: 2018-02-06

Authorized signatory: Wetow Huang

Shenzhen NTEK Testing Technology Co., Ltd. NTEK Report Seal

Shenzhen NTEK Testing Technology Co., Ltd.
Address: 1/F, Building E, Fenda Science Park, Sanwei Community, Xixiang Street, Bao'an District, Shenzhen P.R. China.
Tel: (86)-0755-61156588 Fax: (86)-0755-61156599 Http: www.ntek.org.cn

Test Summary：

No.	Sample Name	Test item	Test request	Conclusion
1	SuperSafeGlas	Salt spray test	After the test, there is no whitening, no discoloration, no bubbles and no turbidity in the sample laminated parts, Rubber parts no crack.	Pass

Test item: Salt spray test

（1）Test equipment：

No.	Name	Model	Calibration validity period
1.	Neutral salt spray test chamber	HK-YW-120	2018-04-09

（2）Reference standard： ASTM B117-16

（3）Laboratory environmental conditions:

Temperature：(23±2)℃，humidity：(50±5)% (RH)

（4）Test conditions：

1) Chamber temperature: 35 ℃, saturated tank temperature: 47℃

2) NaCl concentration: 5%

3) Solution pH: 6.8


4) Test time: 3000h

5) Settlement: 1.6ml / 80cm^2 / h


（5）**Test Results**：

Sample No.	Test result	Test request	Judge
001#	After the test, there is no obvious whitening, no discoloration, no blistering, no cracking and the like in the sample laminated parts.	After the test, there is no whitening, no discoloration, no bubbles and no turbidity in the sample laminated parts, Rubber parts no crack.	Pass
002#	After the test, there is no obvious whitening, no discoloration, no blistering, no cracking and the like in the sample laminated parts.		Pass
003#	After the test, there was no obvious blister, no crack in the sample clamping area, and salt infiltrates about 1mm.		Pass
004#	After the test, there is no obvious whitening, no discoloration, no blistering, no cracking and the like in the sample laminated parts.		Pass
005#	After the test, there was no obvious blister, no crack in the sample clamping area, and salt infiltrates about 1mm.		Pass


（6）Test photo(s):




Pre-test-001#~005#




Testing




After test-001#-1




After test-001#-2




After test-001#-3




After test-001#-4




After test-001#-5




After test-002#-1




After test-002#-2




After test-002#-3




After test-002#-4




After test-002#-5




After test-003#-1




After test-003#-2




After test-003#-3



After test-003#-4




After test-003#-5




After test-004#-1




After test-004#-2




After test-004#-3




After test-004#-4




After test-004#-5




After test-005#-1




After test-005#-2



After test-005#-3



After test-005#-4



After test-005#-5

****End of Report****

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of NTEK, this report can't be reproduced except in full.